

Service Report - Inspection

Name: ARCHER, MATTHEW D & JENNIFER K R/S
Site Address: 13276 APRIL CIR
LOVETTSVILLE, VA
Mail Address: 13276 APRIL CIR
LOVETTSVILLE, VA

Management Level: 4. Alternative Pretreatment System

Service Provider ID:
Service Provider: SeptiCare

Report Filed By: Heather Yamber

System component(s) that were inspected:

Advantex: ☒ <-- Inactive Component as of 5/15/2009 8:25:13 AM
Primary Treatment Tank: ☒ <-- Inactive Component as of 5/15/2009 8:25:13 AM

Date Serviced: 4/15/2009

Notes/Comments/Message or Other Observations: Formal Inspection-VEnt caps need to be replaced and we recommend digging and reparging riser. The panel is not calling in neither and needs to be fixed.

Advantex Questions

**The System Needs Follow Up Service
(Component Replacement or Service,
Components Made Accessible for Inspection or
Sampling, System Pumping, ect.)**

☐ Yes ☒ No

This report only describes the conditions at the time of service and under the conditions of use at that time. This report does not address how the system will perform in the future under the same or different conditions of use.
**This is a copy of an electronic document generated from Carmody.

Question Color Key: (Sample)=Required Question

Copyright © 2010 CDS Holding, Inc.